

FIELD INSPECTION REPORT		
DATE OF INSPECTION:	07/12/2020	DISTRICT: Purnea
DIVISION:	Dhandaha	LENGTH: 1.880 KM
NAME OF THE ROAD:	LOSD to Gulaila Bhatta	
SCHEME/PROGRAMME:	MR-3054	MAINTENANCE
PACKAGE No:	ROAD ID No.:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	N.A
B	CONDITION FO SURFACING	N.A
C	RIDING QUALITY	N.A
D	ROAD CAMBER	N.A
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	N.A
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N.A
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	N.A
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N.A
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATION BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	'S'
4	COMPLIANCE HISTORY	
A	STATUS OF ATR's & ANY OTHERS	N.A
OVERALL RATING	The work yet is to be started	
	SATISFACTORY(S)	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	
	UNSATISFACTORY(U)	

NAME: Surendra Prasad Singh
DESIGNATION: Junior Engineer

Signed
07/12/2020
SIGNATURE