

FIELD INSPECTION REPORT

DATE OF INSPECTION:	07/12/2020	DISTRICT:	Purnea
DIVISION:	Dhanda	LENGTH:	1.800 KM
NAME OF THE ROAD:	L031 to Goriyari Tola		
SCHEME/PROGRAMME:	MR-3054	MAINTENANCE	
PACKAGE No:	ROAD ID No.:		
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SL.NO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	'S'	
B	CONDITION FO SURFACING	'S'	
C	RIDING QUALITY	'S'	
D	ROAD CAMBER	'S'	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	'S'	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N. 4	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	N. 4	
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	'S'	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	'S'	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	'S'	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	'S'	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR"s & ANY OTHERS	N. 4	
OVERALL RATING			
	SATISFACTORY(S)	'S'	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)		
	UNSATISFACTORY(U)		

NAME: Susendra prasad Singh
DESIGNATION: Junior Engineer

SIGNATURE