

FIELD INSPECTION REPORT

DATE OF INSPECTION:	07/12/2020	DISTRICT:	Purnea
DIVISION:	Dhanda	LENGTH:	3.900 KM
NAME OF THE ROAD:	Birnaya chowk Patraha to Phulbariya Mahadalit Tola		
SCHEME/PROGRAMME:	MR-3054	MAINTENANCE	
PACKAGE No:		ROAD ID No.:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SL.NO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	N.A	
B	CONDITION FO SURFACING	N.A	
C	RIDING QUALITY	N.A	
D	ROAD CAMBER	N.A	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	N.A	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	N.A	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	N.A	
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N.A	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	'S'	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR"s & ANY OTHERS	N.A	
OVERALL RATING	The work yet is to be started		
	SATISFACTORY(S)		
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)		
	UNSATISFACTORY(U)		

NAME: Surendra prasad Singh
DESIGNATION: Junior Engineer

SPS-1
07/12/2020
SIGNATURE