	FIELD INSPECTION REPORT	
DATE OF INSPECTION:	08.12.2020 DISTRICT:-PURNEA	
DIVISION:	DHAMDAHA, LENGTH: 18.05 1 <m< td=""></m<>	
NAME OF THE ROAD:	Pupauli to vijay Ghal (MR-OLD)	
SCHEME/PROGRAMME:	MAINTENANCE	
PACKAGE No:	ROAD ID No.:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
Α	ROAD JUNCTION CONDITION	
В	CONDITION FO SURFACING	
С	RIDING QUALITY	
D	ROAD CAMBER	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	*6
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	
2	CROSS DRAINAGE	
Α	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	1 1
В	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	MA
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	
4	COMPLIANCE HISTORY	
Α	STATUS OF ATR'S & ANY OTHERS	<u> </u>
OVERALL RATING	Trong feel ReD	MA
	SATISFACTORY(S) SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	
	LINICATISEA CTORV(II)	

NAME: 1 Cymer honrow DESIGNATION: J.B SIGNATURE INJUNO