

## FIELD INSPECTION REPORT

DATE OF INSPECTION:	08.12.2020 DISTRICT:-PURNEA		
DIVISION:	DHAMDAHA ,LENGTH: 1.44 Km		
NAME OF THE ROAD:	Bhatofar H.S. to Suk Sema.		
SCHEME/PROGRAMME:	MAINTENANCE MR-3054 - OLD		
PACKAGE No:	ROAD ID No.:		
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SL.NO	PARAMETERS TO BE CHECKED		REMARKS
1	<b>PAVEMENT</b>		
A	ROAD JUNCTION CONDITION		/
B	CONDITION FO SURFACING		
C	RIDING QUALITY		
D	ROAD CAMBER		
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT		
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)		
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY		
2	<b>CROSS DRAINAGE</b>		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING		/
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS		
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES		
3	<b>ROAD FURNITURE</b> M.A.		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED		/
4	<b>COMPLIANCE HISTORY</b>		
A	STATUS OF ATR"s & ANY OTHERS		/
OVERALL RATING			
Satisfactory(S)		/	
Satisfactory BUT REQUIRES IMPROVEMENT(SRI)			
Unsatisfactory(U)			

NAME:  
DESIGNATION:

*Kumar Nayson*  
*J.B.*

*Kumar Nayson*  
SIGNATURE 8/12/2020