

FIELD INSPECTION REPORT

DATE OF INSPECTION:	08.12.2020 DISTRICT:-PURNEA		
DIVISION:	DHAMDHAHA ,LENGTH: - 2.96		
NAME OF THE ROAD:	Bazil Bhanslay to shekhpura		
SCHEME/PROGRAMME:	MAINTENANCE (MR-OLD)		
PACKAGE No:	ROAD ID No.:		
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SL.NO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	/	
B	CONDITION FO SURFACING		
C	RIDING QUALITY		
D	ROAD CAMBER		
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT		
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)		
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY		
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	M.A	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	/	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES		
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	/	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR's & ANY OTHERS		
OVERALL RATING	Trans for RCD M.A		
SATISFACTORY(S)		/	
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)			
UNSATISFACTORY(U)			

NAME: Kumar hemson
DESIGNATION: J.B

Signature: Kumar hemson
8/12/2020
SIGNATURE