

FIELD INSPECTION REPORT

Date of Inspection :	5.12.2020	District:	Pune
Division :	BALSI	Length (km):	4.830 KM
Name of the Road:	Rajesh to Phasadpur		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	21105408030
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI NA
c)	Condition of railings/slab/approach for Bridges	S/SRI NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓/Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Except three point damage of Flood.


Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

"S"


(Signature) 5/12/2020

A.E. Baissa

NAME:

Asim Kumar