FIELD INSPECTION REPORT

		FIELD INSPE	CHONICAL	
Date of Inspection : 077-12-2026			District: Soren	
Divisio	The second secon		Length (km) 2.76	
Name	of the Rond:	Kha-tawi -	to Suthfar	
	e/Programme:	MAINTENANCE	Rond Id No.:	
Package No.: Status of the Project:		Ongothg/Completed/Under Maintenance		
		New Connectivity/Up gradation/ Maintenance		
Work is a case of: Sl. No.		Parameters to be checked		Remarks
	-	THE PLANT OF THE PARTY OF THE P	Manager and the second second	and the second
1.	Pavement			SIL
a)	Road Junction condition			✓5/U
b)	Condition of Surfacing			
c)	Riding Quality			√8/U
	Road Camber			~57U
d)	Whether free from defects such as visible cracks, exposed			Yes/No
	aggregates in case of CC Pavement.			Yes/No
n	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any		Cicario	
2.	Cross Draina	ge and storback	A STATE OF THE PARTY OF THE PAR	San High
a)	Condition of head walls in Hume pipe culverts including its painting		s/ski/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			HO
C50 C				

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

NAME: Sudhir Kn. Sigl,
DESIGNATION: A.B.:
Zariopur