## FIELD INSPECTION REPORT

Date o	of Inspection : 07-/2-222 District:	Saray	
Division: D. O. C. Length (km): 6580 /c~			
Package No.: Mc N/ 17- > Chapas/45 Road Id No.:			
Status of the Project: Ongoing/Completed/Onder Maintenance			
Name and Address of the Owner, where the Owner, which is the Owner, where the Owner, which is the Owner, where the Owner, which is the Owner,	Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Yes/No		
f)	Contraction Joints provided or not (CC Pavement)  Yes/No		
g)	Compaction of flank/slope & raincuts if any  Yes/No		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts in	cluding its painting S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in Re	CC culverts S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)		sign boards/informatory/cautionary Board/km & 200m vement road markings are provided and maintained  Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SR	D
Unsatisfactory (U)	

Tender not decided

(Signature) A F

AE Buryayan

NAME:

**DESIGNATION:**