

FIELD INSPECTION REPORT

Date of Inspection : 07.12.2020		District: Saran
Division : Sonpur		Length (km):
Name of the Road: Bighwar Bheldi road to Sakhpauli		
Scheme/Programme: MAINTENANCE		Road Id No.:
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	~S/U
a)	Road Junction condition	~S/U
b)	Condition of Surfacing	~S/U
c)	Riding Quality	~S/U
d)	Road Camber	~S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	~Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	~Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	~S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
21/12/20
(Signature)

NAME: Vinod Kumar Singh

DESIGNATION: J.E
Darjayapur