## FIELD INSPECTION REPORT

Date of Inspection :	06/12/20	District:	Saran	
Division: Marhaura		Length (km):		
Name of the Road: Pachkanda - Brahimpur				
2,011	MAINTENANCE .			
Package No.: RM-SH/MAR-19-0006 Road Id No.: 31306402052				
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Payement	STATE
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No H
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage.	e was
a)	Condition of head walls in Hume pipe culverts including its painting	\$/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.O.

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME: ASHUTOSH KUM AR RAHJAH

DESIGNATION: P.E.