

# FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Saran</u>
Division : <u>Sonpur</u>	Length (km): <u>3.29</u>
Name of the Road: <u>Sitalpur - Parsa road to Mohanmadpur</u>	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	<input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<del>S/SRI/U</del>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Work not Started due to Flood.

NAME: Vinod Kumar Singh  
DESIGNATION: J.E  
Daryapur

(Signature)