FIELD INSPECTION REPORT

Date	of Inspection :	District:		
Divisi	on: Somb	Length	The state of the s	
Name	of the Rond:	HUY PENTA Gihat &	ood to Managarton	1 Mustur
	e-Programme:	MAINTENANCE Road Id	9	
	ge No.:	One ting/Completed/Under Ma		
	of the Project:	New Connectivity/Up gradation	m/ Maintenance	
			Remarks	
Sl. No	Parameters to be cheeked		2.3100-22-2	
1.	Pavement	David Back Street		
a)	Road Junction	condition		8/0
b)	Condition of S	Condition of Surfacing		SAL
c)	Riding Quality		8/4	
d)	Road Camber		S/L	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/Ne_	
n	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2	Cross Drainage			
a)	Condition of he	ad walls in Hume pipe culverts	s including its painting	S/SRI/
b)		outment & Wing walls, Slab in		S/SRL/L
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			
)	Whether sign stones/Pavemen	ooards/informatory/cautionary t road markings are provided	Board/km & 200m and maintained	Yes/No
	Compliance Hi	itory		
) 5	status of ATR's	& any others		NO

Overall Rating

Satisfactory (S)		
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)	125	

(Signature)

Waste not Started due to Blood, ESIGNATION:

:

Darigabus