

FIELD INSPECTION REPORT

Date Of Inspection :

Division: Mahrajganj

Name Of the Road : Ladhi to Chandpur

Scheme/Programme :

MAINTENANCE

Package No. : MR-N/19-20Mahrajganj/07 | Road Id No. :

Status Of the Project :

Ongoing/Completed/Under Maintenance

Work is a case of :

New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be Checked	Remarks
1	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls,Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	→
Unsatisfactory (U)	←

NAME :
DESIGNATION :

ANAND KUMAR
AE

*Atm
5/12/20*
(Signature)

05/12/20
MANISH KUMAR OJHA (J.E.)