		FIELD INSPECTION REPORT	
Pate Of	- Lange	District: Siwan	
Division: Mahrajganj		Anoth/(An) And I	
lame O	f the Road : Pachnaka	Length(KM) : 4.05 km Ariya Dumra More to Dumra Godawan	
TO DO TO TO TO THE TO THE TO THE TO THE TO THE TOTAL TO T			
ackage	No. : MR-N/19-20Ma	MAINTENANCE hrajgani/07   Road Id No.:	
Status O	of the Project :	Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance New Connectivity/Up gradation/ Maintenance	ntenance
Work is a case of :		New Connectivity/Up gradation/ Mai	Remarks
Sl. No.	Day	rameters to be Checked	
1	Pavement	Tameters to No	s/U
	Road Junction condition		s/U
<u>a)</u>	Condition of Surfacing		s/U
<u>b)</u>	Riding Quality		s/U
<u>c)</u>			Yes/No
d)	Road Camber Whether free from defects such as visible cracks, exposed aggregates in		
e)			Yes/No
4)	Contraction loints provided or not (CC ravellion)		Yes/No
f) -\	Compaction of flank/slope & raincuts if any		
g)	D. 10000		s/sri/U
2	Cross Drainage  Condition of head walls in Hume pipe culverts including its painting		
a)	Condition of nead wans	u sieb in RCC culverts	s/sri/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		s/sri/U
	Condition of railings/slab/approach for Bridges		
c)			Yes/No
3	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
a)			
4	Compliance History		No
a)	Status of ATR's & any ot	hers	
		· And	

Overall Rating :

- vi-factory (S)	
Satisfactory (S) Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	

NAME:

DESIGNATION:

ANAND KUMAR

AE

MANISH KUMAR OJHA (J.E.)

- NA