

FIELD INSPECTION REPORT

Date Of Inspection : 5.12.2020 District: Siwan
 Division: Mahrajanj Length(KM) : 3.94 KM
 Name Of the Road : Ojha jee Ke tola to Basao PCC Road
 Scheme/Programme : MAINTENANCE
 Package No. : MR-N/19-20Mahrajanj/07 Road Id No. :
 Status Of the Project : Ongoing/Completed/Under Maintenance
 Work is a case of : New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be Checked	Remarks
1	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.	Yes/No } No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No } Provision
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U } N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NAME :
 DESIGNATION :

ANAND KUMAR
 AE

AKH
 5/12/20
 (Signature)

5/12/20
 MANISH KUMAR OJHA (I.E.)