

FIELD INSPECTION REPORT

Date of Inspection :	5/12/20	District:	Siwan
Division :	Maharajganj	Length (km):	6.50 Km
Name of the Road:	Lilashah Ke pethar to Seewari Port - I		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	Damaged from flood S/U
b)	Condition of Surfacing	" " S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	" Yes/No
g)	Compaction of flank/slope & raincuts if any	" Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	no any

Overall Rating :

Satisfactory (S)	Damaged from flood
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

Sam-Sign Day

NAME: F-E

Signature
5/12/20