

FIELD INSPECTION REPORT

Date of Inspection : 2-12-2020		District: Gopalganj	
Division : HATHUA		Length (km): 7.80 K.M.	
Name of the Road: Bathua Kalyanpur Via Dularpur			
Scheme/Programme:		MAINTENANCE	
Package No.: MR-N-19-20/Hathua-16		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U 'S'	
b)	Condition of Surfacing	S/U 'S'	
c)	Riding Quality	S/U 'S'	
d)	Road Camber	S/U 'S'	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No	N/A
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U 'S'	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes	
4.	Compliance History		
a)	Status of ATR's & any others	not any	

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

RAJARAM PASWAN (J.F.)
ATTAB ALAM BE

DESIGNATION:

(Signature)

2-12-2020
J.F.