

Date of Inspection :	07.12.2020	District:	GOPALGANJ
Division :	HATHUA	Length (km):	10.610
Name of the Road:	Sisai to Bangra Via Rampur.		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20 HATHUA/OB	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N/A S/U
b)	Condition of Surfacing	N/A S/U
c)	Riding Quality	N/A S/U
d)	Road Camber	N/A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	N/A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N/A Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No any

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Surfacing work has not started.

(Signature)
7/12/2020

NAME: Arun Kumar Singh

DESIGNATION: J.E.