## FIELD INSPECTION REPORT

Division: Grobalgant-1		(A)77-1 Length	Length (km): 6.62		
	f the Road:	Khem mathania to Dur	a mathania		
Package	/Programme:	MAINTENANCE	<del></del>	•	
	f the Project:	Road I Ongoing/Completed/Under N		Wook rol	landa
	a case of:	New Connectivity/Up gradat			23/40/19
Sl. No.		Parameters to be check	The Large Co.	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	Remarks
1.	Pavement				
a)	Road Junction condition				S/U
b)	Condition of Surfacing				S/U
c)	Riding Quality				S/U
d)	Road Camber				S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			exposed	Yes/No
f)	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any			ā A	Yes/No
2	Cross Draina	ge			
a)	Condition of head walls in Hume pipe culverts including its painting			painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S	S/SRI/U
c)	Condition of railings/slab/approach for Bridges			* *	S/SRI/U
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			& 200m	Yes/No
4.	Compliance History				ASSITING DIVERSION
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Balane 2020

(Signature)

NAME:

AJAY KUMAR TIWARI

**DESIGNATION:** 

E.E.