

# FIELD INSPECTION REPORT

Date of Inspection : 05-12-2020		District: Gopalganj
Division : RWD Gopalganj - 2		Length (km): 2.00 Km
Name of the Road: Mathiya to Subauli.		
Scheme/Programme:		MAINTENANCE
Package No.:		Road Id No.:
Status of the Project:		<del>Ongoing</del> /Completed/Under Maintenance
Work is a case of:		<del>New Connectivity</del> /Up gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

*[Signature]*  
05-12-20  
(Signature)

NAME: Subhash chandra Verma

DESIGNATION: J.E