

FIELD INSPECTION REPORT

Date of Inspection : - 3/12/20	District : - Muzaffarpur
Division : - R. W. D. Muz. Eng. - I	Length (km):
Name of the Road: Muzaffarpur 2120. Against Mubahani Bazar and Me. Patoli Chauri	
Scheme/Programme:	MAINTENANCE 5. Narayanpur Dalit bank Jak Path Nirma.
Package No.:	Road Id No.: - 31507205005
Status of the Project:	Ongoing/Completed/Under Maintenance — WORK NOT STARTED
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N.A
b)	Condition of Surfacing	S/U N.A
c)	Riding Quality	S/U N.A
d)	Road Camber	S/U N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N.A
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Ravi Singh
3/12/20
(Signature)

NAME: - Kumar Ravindra Prasad Singh

DESIGNATION: - Junior Engineer - Mubahani - I