

Date of Inspection: 07/12/20
 Location: RNB Haxipur.
 Name of Inspector: Vashali
 Length of Road: 2.200 KM
 Nature of Road: Chikarapur to KESDpur
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a part of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincoats if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Signs & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

hole put filling + shoring cleaning
are starting.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

NA

NAME:

[Signature]
 07/12/20
 AC

(Signature)

DESIGNATION: