

FIELD INSPECTION REPORT

Date of Inspection : 05-12-2020	District: Vaishali
Division : Mahanagar	Length (km): 2.76 km
Name of the Road: Udaoli Bighar station to Bhawanani Math via Khokha B45.	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance (Work Not started)
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition N.A	S/U
b)	Condition of Surfacing N.A	S/U
c)	Riding Quality N.A	S/U
d)	Road Camber N.A	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N.A	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N.A	Yes/No
g)	Compaction of flank/slope & raincuts if any N.A	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N.A
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Work Not started.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)
Shankumar
5/12/20

NAME: Shailendra Kumar.

DESIGNATION: J.E RWD, Desai