FIELD INSPECTION REPORT

Date of	Inspection:	311-1311	ength (km): 2,	uhi	
Division	: M	hner	The second secon	25 100	
	f the Road:	Jurawanpus to E	Shuifan Sthe	C 8 (+	
		MAINTENANCE	oad Id No.:		
Package	No.:	La 'Gampleted/U	nder Maintenance	mas Pr	ociss
Status o	f the Project:	New Connectivity/Up a	gradation/ Maintenan	ce	
CONTRACTOR OF THE	a case of:	Parameters to be	checked	The same of the sa	Remarks
Sl. No.	and the second second	Parameters co		حدلمسينسس	
1.	Pavement			A STATE OF THE STA	CAI
a)	Road Junction condition			NA	S/U
	Condition of	on of Surfacing NA			S/U
b)				S/U	
c)	Riding Qualit	у			S/U
d)	Road Camber			NA	5/ 0
	Whether free from defects such as visible cracks, exposed				
e)	aggregates in	ates in case of CC Pavement.			
f)	Contraction J	Joints provided or not (CC Pavement)			Yes/No
	1				Yes/No
g)	Compaction of A				
2.	Cross Drain	ige	Ten and the second seco		CIODIAI
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
	Condition of Abutment & Wing walls, Slab in RCC culverts			1 0/01/1/1	
b)					C/CDI/I
c)	Condition of	railings/slab/approach f	Of Duringes	NA	Miles Alexander Total
3.	Road Furnit	ure			Later Transcription Control of the Control
				1 77	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/in
					THE STATE OF THE S
4.	Compliance	History			No. of the second
		?'s & any others			NO
a)	Status of A11	C S & dily others	^	C15 8006	. Il

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: NAND KISHOR SHARMA
DESIGNATION: j. e., Rugeropur