

FIELD INSPECTION REPORT

Date of Inspection : 7/12/20	District: VAISHALI
Division : MAHAR	Length (km): 3.07
Name of the Road: Bindichowk (Manginhpur to Gishauli) to Loma	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 31507708019
Status of the Project: Ongoing/Completed/Under Maintenance	out of maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ N.A
b)	Condition of Surfacing	S/U N.A
c)	Riding Quality	S/U N.A
d)	Road Camber	S/U N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U N.A
c)	Condition of railings/slab/approach for Bridges	S/SR/U N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NO.
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating : out of maintenance

Satisfactory (S)	
Satisfactory but requires Improvement (SRU)	
Unsatisfactory (U)	

Signature
7/12/20

ME: Vajayshankar Singh