

# FIELD INSPECTION REPORT

| Date of Inspection : 1.12.20                |                                                                                                                      | District: SITAMARHI                                |  |
|---------------------------------------------|----------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|--|
| Division : BELSAND                          |                                                                                                                      | Length (km): 1.13                                  |  |
| Name of the Road: LUKH BAZAR - KHARKA GANDH |                                                                                                                      |                                                    |  |
| Scheme/Programme:                           |                                                                                                                      | MAINTENANCE                                        |  |
| Package No.:                                |                                                                                                                      | Road Id No.:                                       |  |
| Status of the Project:                      |                                                                                                                      | Ongoing/Completed/Under Maintenance/Tender Process |  |
| Work is a case of:                          |                                                                                                                      | New Connectivity/Up gradation/ Maintenance         |  |
| Sl No.                                      | Parameters to be checked                                                                                             | Remarks                                            |  |
| 1.                                          | <b>Pavement</b>                                                                                                      |                                                    |  |
| a)                                          | Road Junction condition                                                                                              | SU                                                 |  |
| b)                                          | Condition of Surfacing                                                                                               | SU                                                 |  |
| c)                                          | Riding Quality                                                                                                       | SU                                                 |  |
| d)                                          | Road Camber                                                                                                          | SU                                                 |  |
| e)                                          | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No                                             |  |
| f)                                          | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No                                             |  |
| g)                                          | Compaction of flank/slope & raincuts if any                                                                          | Yes/No                                             |  |
| 2.                                          | <b>Cross Drainage</b>                                                                                                |                                                    |  |
| a)                                          | Condition of head walls in Hume pipe culverts including its painting                                                 | SSRIU                                              |  |
| b)                                          | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | SSRIU                                              |  |
| c)                                          | Condition of railings/slab/approach for Bridges                                                                      | SSRIU                                              |  |
| 3.                                          | <b>Road Furniture</b>                                                                                                |                                                    |  |
| a)                                          | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No                                             |  |
| 4.                                          | <b>Compliance History</b>                                                                                            |                                                    |  |
| a)                                          | Status of ATR's & any others                                                                                         |                                                    |  |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

*[Signature]*

(Signature)

NAME: GIRISH PRASAD SAH

DESIGNATION: S.E

MC

NIA