FIELD INSPECTION REPORT

Date of Inspection: 04 12/2020 .			District: EAST CHAMPARAN	
Division: MOTIHARI			gth (km): 2.050 1cm.	The state of
		MOTIHARI AJAGIARI A	CEO ROAD TO SISWA	•
Scheme/Programme: MAINTENANCE			- New Mountenance Policy - 2018	
Package	A SECOND	Ros	d Id No.:	
		Ongoing/Completed/Und		
CANADA NES ASSESSAS	a case of:	New Connectivity/Up gra	dation/ Maintenance	
Sl. No.	Parameters to be checked R			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges S/SRI/			S/SRI/U
· 田田寺大大学の下中の日の一覧をごうなす	THE CONTRACT CONTRACT OF THE PROPERTY OF THE P			

Whether sign boards/informatory/cautionary Board/km & 200m

stones/Pavement road markings are provided and maintained

Overall Rating

a)

4.

a)

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

REMARKS! WORK HAS NOT BEEN STARTED.

(Signature)

Yes/No

NAME: AKHILESH PRASAD.

Road Furniture

Compliance History
Status of ATR's & any others

DESIGNATION: A.E. WORKS SUB-DIVISION, BANJARIYA .

(MOTIHARI DIVISION)

NAME - ABHIMANYU TANTI

DESIGNATION: J.E, BANJARIYA KOT.NA

07/142020 JE NA.