

FIELD INSPECTION REPORT

Date of Inspection: 07/12/20 District: East Champaran
 Division: Motihani Length (km): ~~6.90~~ 6.670 KM
 Name of the Road: Shitalpur Dhala To Jatwa Janewa Uhat
 Scheme Programming: (New)
 Package No.: — Road Id No.: —
 Status of the Project: ☒ Complete ☐ Under Maintenance
 Work is a case of: ☒ New ☐ Extension ☐ Rehabilitation ☐ Modification

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
	Overall pavement condition	SU NA
	Condition of Surfacing	SU NA
	Riding Quality	SU NA
	Road Camber	SU NA
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
	Contraction Joints provided or not (CC Pavement)	Yes/No NA
	Compaction of flank slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Sign board, Yes/No informatory board provided
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

'S'

DPR of above road is under revision vide E.E. letter No-889, dtd-26.05.2020 submitted to S.E due to Flood 2020.

[Signature]
 07/12/20
 (Signature)

NAME: Baidyanath Kumar

DESIGNATION: J.E