


FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020		District: East Champaran	
Division : Mofikari		Length (km): 3.541	
Name of the Road: Madhumalat RFO Road to Belwahia			
Scheme/Programme: MAINTENANCE		MA-3054 (New)	
Package No.:		Road Id No.:	
Status of the Project: ☒ Ongoing/Completed/Under Maintenance			
Work is a case of: ☒ New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U N.A
b)	Condition of Surfacing		S/U N.A
c)	Riding Quality		S/U N.A
d)	Road Camber		S/U N.A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)		Yes/No N.A
g)	Compaction of flank/slope & raincuts if any		Yes/No N.A
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges		S/SRI/U N.A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		N.A

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NOTE: Work yet to start


07/12/2020
(Signature)

NAME: Anil K. P. Thakur

DESIGNATION: J.E