

## FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District : E. Champaran.
Division : Chokri		Length (Km): E. Champaran 2.0708
Name of the Road : NH-28 to Damodarpur		
Scheme/Programme :		MAINTENANCE (New)
Package No.:		Road ID No.:
Status of the Project :		<input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance
Work is a case of :		<input checked="" type="checkbox"/> New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	- S -
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	-
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :	Satisfactory (S)	S
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	

NAME :

DESIGNATION :

*Abhi*  
03/12/2020  
JE

(Signature)