

FIELD INSPECTION REPORT

Date of Inspection :	7/12/20	District:	East Champaran
Division :	Raxaul	Length (km):	1.83
Name of the Road:	NH28A to Sonarpur		
Scheme/Programme:	MAINTENANCE OR-3054 (New Halyd. Policy 2018)		
Package No.:	16	Road Id No.:	31708202144
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRLU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRLU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Note: - Work has not been started.

M. K. Singh
7/1/20
(Signature)

NAME: *M. K. Singh*

DESIGNATION: *Senior Engineer, Raxaul*