


FIELD INSPECTION REPORT

Date of Inspection : 07-12-2020		District : East Champaran	
Division : RWD Chalcia		Length (Km): 2.714	
Name of the Road : Panchachakra RD Road to Sirsi'a			
Scheme/Programme :		MAINTENANCE	
Package No.:		Road ID No.: 31708202185	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1,	Pavement		
a)	Road Junction condition		S
b)	Condition of Surfacing		S
c)	Riding Quality		S
d)	Road Camber		S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes
f)	Contraction Joints provided or not (CC Pavement)		-
g)	Compaction of flank/slope & raincuts if any		-
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		Yes
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		-
c)	Condition of railings/slab/approach for Bridges		-
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained		No
4,	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	-
	Satisfactory but requires improvement (SRI)	SRI
	Unsatisfactory (U)	-


 (Signature)

NAME :

DESIGNATION :