


FIELD INSPECTION REPORT

Date of Inspection : 07-12-20		District : East Champaran	
Division : Chakia		Length (Km): 5.74	
Name of the Road : RFO Road near Bhumai Chhapra			
Scheme/Programme :		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1,	Pavement		
a)	Road Junction condition	- S/A -	
b)	Condition of Surfacing	- S/A -	
c)	Riding Quality	- N/A -	
d)	Road Camber	- N/A -	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-	
f)	Contraction Joints provided or not (CC Pavement)	-	
g)	Compaction of flank/slope & raincuts if any	-	
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	- N/A -	
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-	
c)	Condition of railings/slab/approach for Bridges	-	
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	- N/A -	
4,	Compliance History	-	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires improvement (SRI)	-
Unsatisfactory (U)	-

Work not started. Letter has been issued.


 7/12/20
 (Signature)

NAME :

DESIGNATION :