


FIELD INSPECTION REPORT

| Date of Inspection : 05-12-20 | | District : East Champara |
|--|---|--|
| Division : Chulchra | | Length (Km): 2.069 |
| Name of the Road : Rto Road to Bakheri | | |
| Scheme/Programme : | | MAINTENANCE |
| Package No.: | | Road ID No.: |
| Status of the Project : | | Ongoing/Completed/Under Maintenance |
| Work is a case of : | | New Connectivity/Up Gradation/ Maintenance |
| Sl. No. | Parameters to be checked | Remarks |
| 1, | Pavement | |
| a) | Road Junction condition | NA |
| b) | Condition of Surfacing | NA |
| c) | Riding Quality | NA |
| d) | Road Camber | NA |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | NA |
| f) | Contraction Joints provided or not (CC Pavement) | - |
| g) | Compaction of flank/slope & raincuts if any | - |
| 2, | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | NA |
| b) | Condition of Abutment & Wing walls, Slab in RCC Culverts | - |
| c) | Condition of railings/slab/approach for Bridges | - |
| 3, | Road Furniture | |
| a) | Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained | NA |
| 4, | Compliance History | |
| a) | Status of ATR's & any others | - |

Overall Rating :


| | |
|---|---|
| Satisfactory (S) | - |
| Satisfactory but requires improvement (SRI) | - |
| Unsatisfactory (U) | - |

Work not started. Letter has been issued

(Signature) 

NAME :

DESIGNATION :


5.12.2020