

FIELD INSPECTION REPORT

Date of Inspection : 07-12-20		District : East Champaran	
Division : Chackia		Length (Km): 2.210	
Name of the Road : Rajpur PWD Road to Bisupurhatti			
Scheme/Programme :		MAINTENANCE	
Package No.:		Road ID No.:	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1,	Pavement		
a)	Road Junction condition		- NA -
b)	Condition of Surfacing		- NA -
c)	Riding Quality		- NA -
d)	Road Camber		-
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		-
f)	Contraction Joints provided or not (CC Pavement)		-
g)	Compaction of flank/slope & raincuts if any		-
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		-
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		-
c)	Condition of railings/slab/approach for Bridges		-
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained		- NA -
4,	Compliance History		
a)	Status of ATR's & any others		-

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SRI)

Unsatisfactory (U)

Remarks: - Work not started. Letter has been issued.

(Signature)

NAME :

DESIGNATION :