

FIELD INSPECTION REPORT

Date of Inspection: 07/12/2020 District: East Champaran.
 Division: Motihani Length (km): 0.710 Km
 Name of the Road: Bhargawa To Bandha Kurbaini
 Scheme Programme: MAHARASHTRA (New)
 Package No.: — Road Id No.: —
 Status of the Project: ☒ Minor Complete ☐ Minor Maintenance
 Work is a case of: ☒ New Construction ☐ Upgradation ☐ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Overall surface condition	SI NA
b)	Condition of Surfacing	SI NA
c)	Binding Quality	SI NA
d)	Road Camber	SI NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Sign board Yes/No informatory board provided
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

'S'

pot/patch work in progress.

07/12/20
(Signature)

NAME: Baidyanath Kumar.

DESIGNATION: J.E