

FIELD INSPECTION REPORT

Date of Inspection :	07/12/20	District:	East Ghazipur
Division :	Mohi Kari	Length (km):	8.35 K.M.
Name of the Road:	Belwara to Baigaji R.O. road to Barharwa		
Scheme/Programme:	MAINTENANCE	(New Maintenance Policy)	
Package No.:	-	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N.A.
b)	Condition of Surfacing	S/U N.A.
c)	Riding Quality	S/U N.A.
d)	Road Camber	S/U N.A.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Sign boards/ Yes/No Informatory Board Cautionary Board
4.	Compliance History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	" S "
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

Work is in progress

(Signature) 7/12/20

NAME: MAHESHWAR SHARMA
DESIGNATION: J.E.