

FIELD INSPECTION REPORT

Date of Inspection: 07/12/2020 District: East Champaray
 Division: Motihari Length (km): 1.40 km
 Name of the Road: TOY TO Dharampur
 Scheme Programme: MAINTENANCE (New)
 Package No.: — Road Id No.: —
 Status of the Project: ☒ Complete ☐ Under Maintenance
 Work as a case of: ☐ New ☐ Concessions ☐ Upgradation ☒ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road surface condition	SA NA
b)	Condition of Surfacing	SA NA
c)	Riding Quality	SA NA
d)	Road Camber	SA NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRIU NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRIU NA
c)	Condition of railings/slab approach for Bridges	S SRIU NA
3.	Road Furniture	
a)	Whether sign boards/informatory cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	informatory sign board provided. Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)

'S'

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

pot/patch work in progress.


 07/12/20
 (Signature)

NAME: Baidyanath Kumar

DESIGNATION: J.E