

FIELD INSPECTION REPORT

Date of Inspection : 07-12-20		District : East Champaran
Division : Chacki's		Length (Km): 2.00
Name of the Road : Purnea Chhapra to Koesganj		
Scheme/Programme :		MAINTENANCE
Package No.:		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	NA
b)	Condition of Surfacing	NA
c)	Riding Quality	- NA -
d)	Road Camber	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	-
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	-
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	- NA -
4,	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :	Satisfactory (S)	-
	Satisfactory but requires improvement (SRI)	-
	Unsatisfactory (U)	-

Work not started. letter has been issued.

(Signature)  7/12/20

NAME :

DESIGNATION :