

FIELD INSPECTION REPORT

Date of Inspection : 08/12/2020		District: East Champaran
Division : Ayeyaj		Length (km): 2.90
Name of the Road: T6 to Kori tola		
Scheme/Programme: MAINTENANCE		
Package No.: MR-N/19-20 Ayeyaj-25		Road Id No.: 31708302014
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	Tender process
a)	Road Junction condition	Under Tender Disposal
b)	Condition of Surfacing	process
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME:

Harsh Sah

DESIGNATION:

A.E. RWD -
Ayeyaj

Scanned with CamScanner