


# FIELD INSPECTION REPORT

Date of Inspection : 07-12-20		District : East Champaran
Division : Chakra		Length (Km): 0.560
Name of the Road : Raudihra to Koile Belwa.		
Scheme/Programme :		MAINTENANCE
Package No.:		Road ID No.:
Status of the Project :		Ongoing/Completed/Under Maintenance
Work is a case of :		New Connectivity/Up Gradation/ Maintenance
Sl. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	NA
b)	Condition of Surfacing	NA
c)	Riding Quality	NA
d)	Road Camber	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	- NA -
f)	Contraction Joints provided or not (CC Pavement)	-
g)	Compaction of flank/slope & raincuts if any	-
2,	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	-
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	-
c)	Condition of railings/slab/approach for Bridges	-
3,	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	- NA -
4,	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :	Satisfactory (S)	-
	Satisfactory but requires improvement (SRI)	-
	Unsatisfactory (U)	-

Road not started. letter has been issued.

  
 (Signature) 07/12/20

NAME :

DESIGNATION :