FIELD INSPECTION REPORT

Date of Inspection; 87 12/20			Length (Km): 2.270	
COURTS &		08 to Januar	DNL	
Contract of	Programme :	MAINTENANCE	d ID No.: 31708403	2013
ackage				
tatus of	f the Project :	Ongoing/Completed/Under Ma	and the second second second	
ork is	a case of :	New Connectivity/Up Gradation	on/ Maintenance	Remarks
l. No.	Parameters to be checked			Kelliaiks
1,	Pavement			NA
a)	Road Junction condition			Carlotte C
b)	Condition of Surfacing			NA
c)	Riding Quality			NA
d)	Road Camber			NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			NA
f) _	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any Cross Drainage			
2,				
a)	Condition of head walls in Hume pipe culverts including its painting			At A
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts			## / ## / ## / ## / ## / ## / ## / ##
c)	Condition of railings/slab/approach for Bridges			111111111111111111111111111111111111111
3,	Pood Furniture			
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			l NA
4,	Compliance History			
a)	Status of ATR's & any others			
	Overall Rating :	Satisfactory (S) Satisfactory but requires im Unsatisfactory (U) Letter has h		

MAME

DESIGNATION