

FIELD INSPECTION REPORT

Date of Inspection : 07-12-20		District : East Champaran	
Division : Chakia		Length (Km): 7.50 km	
Name of the Road : Vrindavan Road se Kalyanpur Path			
Scheme/Programme :		MAINTENANCE	
Package No.:		Road ID No.: 31708408027	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up Gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1,	Pavement		
a)	Road Junction condition		S
b)	Condition of Surfacing		U
c)	Riding Quality		S
d)	Road Camber		S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		NO
f)	Contraction Joints provided or not (CC Pavement)		-
g)	Compaction of flank/slope & raincuts if any		-
2,	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		-
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts		-
c)	Condition of railings/slab/approach for Bridges		-
3,	Road Furniture		
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained		NO
4,	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	
	Unsatisfactory (U)	U

①. few Chaugy damage due to flood 2020. Road is maintained under FDR. DPR is under process for restoration

NAME :

DESIGNATION :

(Signature) 7/12/20