

New Maintenance.

# FIELD INSPECTION REPORT

|                        |                                              |             |          |
|------------------------|----------------------------------------------|-------------|----------|
| Date of Inspection:    | 02/12/XX                                     | District:   | Motihari |
| Division:              | Pakari Dayal                                 | Length(Km): |          |
| Name of Road:          | Hathiaul Thari Lal Rd. mandir to Har Nathpur |             |          |
| Scheme/Programme:      | Maintenance ✓                                |             |          |
| Package No.            |                                              | Road Id No. |          |
| Status of the Project: | Ongoing/Completed/ Under Maintenance ✓       |             |          |
| Work is a case of :    | New Connectivity/Up gradation/ Maintenance ✓ |             |          |

| S No.    | Parameters to be Checked                                                                                                 | Remarks   |
|----------|--------------------------------------------------------------------------------------------------------------------------|-----------|
| <b>1</b> | <b>Pavement</b>                                                                                                          |           |
| a)       | Road Junction condition                                                                                                  | ✓ S/U     |
| b)       | Condition of Surfacing                                                                                                   | ✓ S/U     |
| c)       | Riding Quality                                                                                                           | ✓ S/U     |
| d)       | Road Camber                                                                                                              | ✓ S/U     |
| e)       | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement                              | ✓ Yes/No  |
| f)       | Contraction Joints provided or not (CC Pavement)                                                                         | ✓ Yes/No  |
| g)       | Compaction of flank /slope & raincuts if any                                                                             | ✓ Yes/No  |
| <b>2</b> | <b>Cross Drainage</b>                                                                                                    |           |
| a)       | Condition of head walls in Hume pipe culverts including its painting                                                     | ✓ S/SRI/U |
| b)       | Condition of Abutment & Wing walls , Slabs in RCC culverts                                                               | ✓ S/SRI/U |
| c)       | Condition of railing /slabs/ approach for Bridges                                                                        | ✓ S/SRI/U |
| <b>3</b> | <b>Road Furniture</b>                                                                                                    |           |
| a)       | Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained | ✓ Yes/No  |
| <b>3</b> | <b>Compliance History</b>                                                                                                |           |
| a)       | Status of ATR's & any others                                                                                             |           |

Overall Rating:

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | ✓ S |
| Satisfactory but requires Improvement (SRI) |     |
| Unsatisfactory (U)                          |     |

ON Going Scheme.

Name:

Designation:

(Signature)

*[Signature]*  
02/12/XX  
OE/Plr.