

FIELD INSPECTION REPORT

Date of Inspection : 07/12/2020	District: W. Champaran
Division : Belhiya	Length (km): 5.750 Km
Name of the Road: Mangaulia road Bank to RT Road	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 318088 0 8073
Status of the Project: Ongoing/Completed/Under Maintenance	Under Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Payement	
a)	Road Junction condition	S
b)	Condition of Surfacing	U
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

SB
07/12/20

(Signature)

NAME: SUNIL DATTA

DESIGNATION: AE