

FIELD INSPECTION REPORT

Date of Inspection : 04.12.2020		District: W. Champaran	
Division : Ballia		Length (km): 6.50	
Name of the Road: Pipla Samaria to Lalgaath Path			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance 1/3 Progress	
Work is a case of:		New Connectivity/Up gradation/ Maintenance Maint.	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	N/A	
b)	Condition of Surfacing	N/A	
c)	Riding Quality	N/A	
d)	Road Camber	N/A	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—	
f)	Contraction Joints provided or not (CC Pavement)	—	
g)	Compaction of flank/slope & raincuts if any	—	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	—	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—	
c)	Condition of railings/slab/approach for Bridges	—	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N/A	
Compliance History			
a)	Status of ATR's & any others	ND	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

U

Note:- Road taken in busy phase-II
work is on tender basis

[Signature]
(Signature)

NAME: SUNIL KUNAR

DESIGNATION: J.E