

Date of inspection: 3-12-20
Inspector: S.P.R. 20 Gullath.
Name of the Road: Balua to Jirasia

Dist - West Garo region
Length: 2.6 km

Package No.: Road Id No.: 31905 801014


Status of the Project: ☒ New ☐ Upgradation/Maintenance

Work is a case of: ☒ New ☐ Upgradation/Maintenance

S. No.	Parameter to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No H/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No H/A
g)	Compaction of flank/slope & alcuts if any	Yes/No ☒
2.	Cross Drainage	
a)	Condition of box walls in case of pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & box walls, Slab in RCC culverts	S/SRI/U
c)	Condition of rafts/slabs/abutment for Bridges	S/SRI/U
3.	Other features	
a)	Whether sign boards/informatory/cautionary board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
b)	Complete barrier	
c)	Use of ATR's & barriers	No

Overall Rating:

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: Rudra Bera

DESIGNATION: J E