## FIELD INSPECTION REPORT

Date	of Inspection:	TASOD WASHE	CTION REPORT	
-	150/101	0112020	~ .	
Nam	e of the Dank		District: W. Chan Bara	n
Sche	me/Programme:	ans burne to	Length (km): 1.1010.	A Company of the Comp
Pack	age No.:	MAINTENANCE	THE TAIL	The set Transaction in the Section of the section o
Statu	s of the Project:		Road Id No.: 3. Boggog	the afficient is surely to information the second control of the financial state of the second
Worl	is a case of:	Ongoing/Completed	/Under Maintenance UNDS  p gradation/ Maintenance	069
SL N			- The state of the	Mach.
		Parameters to	be checked	D
1. Payement				Remarks
a)	Road Junction c	ondition		
b) Condition of S				ı S/U
c)	Riding Quality	racing	\$	- S/U
d)	Road Camber		(	· S/U
<del></del>			\$	S/U
e)	Whether free f	from defects such e of CC Pavement.	as visible cracks, exposed	Yes/No
f)	Contraction Joint	s provided or not (CC	Pavement) Yes	Yes/No
g)	Compaction of fla	nk/slope & raincuts i	fany Yel	Yes/No
2	Cross Drainage			1
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			
)		rds/informatory/cauti ad markings are prov	onary Board/km & 200m ided and maintained	Yes/No
	Compliance Histor	y		
	Status of ATR's & a	nny others		NO

Overall Rating

Satisfactory (S)	7
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: SUNIC RUHAR

DESIGNATION:  $\mathcal{J}^{-\varepsilon}$