## FIELD INSPECTION REPORT

Date of Inspection :	08 12 2020	District: Madhubani	
Division: Madhuba	<del>ว</del> ท1	Length (km): 2.300 km	
Name of the Road:	retorate to	Mohampyr	
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	s/u s
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ^
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N
g)	Compaction of flank/slope & raincuts if any	Yes/No Y
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U 9
c)	Condition of railings/slab/approach for Bridges	s/sri/u s
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No >
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

5 11 C ( (C)	-
Satisfactory (S)	001
Satisfactory but requires Improvement (SRI)	319
Unsatisfactory (U)	

Note- work not started by contractor

(Signature)

NAME: AShor proceed simply DESIGNATION: AE, pandaul